STS-135/ULF7

FD 07 Execute Package



MSG	Page(s)	Title
051	1 - 15	FD07 Flight Plan Revision
052	16 - 17	FD07 Mission Summary
053	18 - 19	FD07 Transfer Message
054	20 - 24	Resupply Stowage Platform (RSP) Strut R&R

Approved by FAO:

J. Mintz

Approved by OpsPlan:

K. Howel

Last Updated: Jul 14 2011 4:08 AM GMT **JEDI** (**J**oint **E**xecute package **D**evelopment and **I**ntegration), v3.0



Top 10 reasons O3 FDO was late today:

- 10. Coasting, what's the hurry.
- 9. Too many DAMs on the way to work today
- 8. He's traumatized by flight asking what the NOTAMs mean
- 7. Orbit 3 hours are rough, he wishes he was on Orbit 1
- 6. His home OIGN- clock was set incorrectly
- 5. He was pulled over on the way in and the officer asked "Do you know how fast you were going?" FDO responded "In which reference frame?"
- 4. Pink shirt was still in the dryer
- 3. Handover is non-critical and can be slipped in one rev increments
- 2. The next burn isn't until FD12, what is he even here for?
- 1. Over-burned leaving a stoplight and ran out of gas



MSG 051 (28-0550) - FD07 FLIGHT PLAN REVISION

Page 1 of 15

1 2 3

4

5

6

MSG INDEX

TITLE MSG NO.

FD07 Flight Plan Revision 051 052 FD07 Mission Summary 053 FD07 Transfer Message

054 Resupply Stowage Platform (RSP) Strut R&R

7 8 9

1. Due to continually running ~700 watts under the predicted power level, margin is now 8 hours.

10 11 12

13

For today's cryo config, O2 tanks 2 & 4 and H2 tanks 2 & 5 will be active. H2 tank 5 may deplete today, so there may be a post-depletion cryo reconfig before the pre-sleep config tonight.

14 15 16

R1 O2,H2 MANF VLV TK2 (two) - OP (tb-OP)

A11 CRYO TK4 HTR O2 B - OFF

17 18 19

20

21

2. WHC/WCS OPS: WHC is operational and you can resume usage at your convenience. Use of the WHC versus the WCS will build further margin in the waste tank and assist ISS. Since Waste H2O rates are below predicts, the postundocking Condensate CWC dump will be deleted.

22 23 24

3. **Fergy:** We copied Sandy's comment during the transfer brief yesterday about the broken #10 Torque Tip but we need some clarification - Was this the Torque Tip Driver, 3/8-in Drive or the Torque Tip Screwdriver?

26 27 28

29

30

31

25

4. The TriDAR team would like to thank you for your excellent troubleshooting on FD03 and is happy to report that they have received great data. More than 70,000 data and telemetry files have been downlinked from the PGSC and the support team is busy pouring over the data. Early analysis indicates that the system has outperformed the docking results received from STS-128 and STS-131.

32 33 34

5. Below is information about the Santiago ground station for the ground pass at MET 5/18:25:54

35 36 37

38

39

40

41

The Santiago station provided on-orbit communication support for early shuttle flights. then left the Space Shuttle family as the TDRS satellite network developed and matured. In recent years the Santiago site was asked to support shuttle flights once again, allowing the flight control team to maximize use of the K-Band communication link via the TDRS satellites. Santiago has provided excellent support and their efforts are appreciated.

42 43 44

45

6. Crew Choice Downlink KU Opportunities:

46

Please allow 1-2 minutes to lock up on Ku-band. Check with MCC before starting playback.

47 48 49

Pre-Sleep Evening of FD07

TDRS	AOS	LOS	Delta (min)	Notes
W-171	6/02:05	6/02:39	34	
E-TDS	6/04:27	6/04:53	26	

50 51

7. Replace Pages 2-22 through 2-25 and 3-68 Through 3-77.


GMT)7 07/14/11 (195)	04 05	06 07	08	09	10	' ''' 11	12	13		14 15
MET	Day 005	.2 13 1	15 16	17	18	19	لبيا	20	21	22	23 006/00
	CDR FERGUSON	SLEEP	POST SLEEP	U AFER	EXERCISE	^AGOS,18:25	PAO HD	MPLM XFER	MEAL	PAO HD	OFF PFC OFF DUTY OCA
S T S	PLT HURLEY	SLEEP	POST SLEEP	I W # P	N 2 MPLM XF	C C W C C # FER T 8 EXE EXE T N M I T	RCISE	CWC XFERM	MEAL	PAO HD	OFF DUTY
1 3 5	MS1 SLEEP MAGNUS		T U R P A D M N A D S T D F E M E R	POST SLEEP	МР	LM XFER	PAO HD	EXERCISE	MEAL	PAO HD	OFF DUTY
	MS2 WALHEIM	SLEEP	POST SLEEP	EXERCISE		MPLM XFE	R		MEAL	PAO HD	OFF DUTY
	DAY/NIGHT ORBIT				01						
	W	87 88	89 9	0	91	92			93	_	94 95
TDRS E Z											
100	ORB ATT ISS TDRS AVAIL										
130	<u> </u>	-		*POD H	TR RECONFIC	G					
	Notes										


F G	D07	07/14/11 (195)	04 05 2 13 1			1,6			10	1 ₉	11	12 20	13 21	14 22	15 23 006/00
M	ET	Day 005	2 13 1	4 15	Lu	سأنسا	1 7	18	111	سأس	1		<u> </u>		
		ISS CDR BORISENKO	SLEEP	POST SLEEP	DPC	PW CN	S-TVIS GYRO-PT1	C S C G M P M Y S D S R 0 T T T T - V R V R I Q I & S S R	PT3	D A K - V F Y	DAKON DNLD		ARED	MEAL	Т2
		FE-1 SAMOKUTYAEV	SLEEP	POST SLEEP TO DPC PREP		Б I М N П I Ф T 2	PW	A	AK-1M A SAMPL S BU1 M P	R P H A A S M S	(сож	T2	MEAL	С И О П ГФИ С 1 17 D / L M END N END
		FE-3 GARAN	SLEEP	S A L L I POST SLEEP V A	DPC	PW	ARED ,	C 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	N2S-(CQ-CLI	EAN	WW OFFLI	0 2 F F L D		OFF DUTY
	I S S	FE-4 SLEEP VOLKOV		POST SLEEP	DPC	PW CN	S-TVIS GYRO-PT1	C G M Y S R - 0 T - V R I & S R	PT3	R P H A A S M S	CMS TVIS SPEED CHAR	Φ	VELO	MEAL	OFF DUTY
		FE-5 FURUKAWA	SLEEP	S A L I POST SLEEP V A	DPC	PW	MPLM XFER	ARI	ED	P A O S / U	MPLN	1 XFER	♦ ® ∀ Δ	MEAL	P A O O OFF DUTY D
		FE-6 FOSSUM	SLEEP	S A L I POST SLEEP V A	DPC	PW	V C A A • T	2	ф		ONDS MPL	•	PR ATT ON LP TRM SV /C UA	MEAL	OFF DUTY
	F	DAY/NIGHT DAILY ORBIT	14 15	1			2	2			4		5	6	7
	ŀ	TDRS AVAIL	14 13	1			۷	<u> </u>			4		3	0	/
E		ISS TIM	122						<u> 112 - </u>						122
		ORBIT NOTES	87 88	89			90 •EMU-LOOP SO	91 CRUB-INIT			92 TTC-УКВ CRUB-RC	ZД-C/O ⊕TVIS DNL NFG •HTCH STOW	♥CSF	94 THR3 SMPL-PREP PN-2MEU-ATTACH CSPN-MELFI-AAE	


	ሰበሩ	16 17	18 19 20	21 22 23 07/15 01 02 03					
MET	Day 006	/00 01 02	03 04 09						
	CDR FERGUSON	OFF DUTY	A C E H M E S C S K T SLEEP A/G T U S	SLEEP					
S T S	PLT HURLEY	OFF DUTY PFC OFF DUT OCA	I L Y L PRE SLEEP O N	SLEEP					
1 3 5 5	MS1 MAGNUS	OFF DUTY	TB RR TB RR RR AI RR NE AI SF NE FF SF ER ER RE R	SLEEP					
	MS2 WALHEIM	OFF DUTY OCA	M D PRE SLEEP K	SLEEP					
	DAY/NIGHT ORBIT	95 1 96	97 98	99 100 101 102 103					
ТС	DRS E Z ORB ATT	95 96	97 98	99					
ISS	TDRS AVAIL			DIO -VEA - CAA					
	Notes								


FD(GMT	07/14/11 (195)	 16 /00	17	111111	1	8 1	.9		20 21 22 23 07/15 01 02 03
MET	Day 006	700 	01	02	أنبا	03	0 	<u>"</u>	05 06 07 08 09 10 11 12
	ISS CDR BORISENKO	Т2	DPC	PRE SLI	EEP-ISS	;	SLEEP		
	FE-1 SAMOKUTYAEV	ГФИ PRP	VELO	PW	DPC	PS	БМП Ф2 END	l ra	SLEEP
	GARAN	I IPI - II IWI I I-I				PRE SLP C N	PRE	SLP (SLEEP
S S		O V A A A A A A A A A A A A A A A A A A				PRE SLEI	EP-ISS	М Б И I N I Т	SLEEP
	FE-5 FURUKAWA	OFF DUTY ♣ T2 PW ⊕DP				PREPMC PRE SLEEP-ISS SLP			SLEEP
	FE-6 FOSSUM					PRE SLI		; [SLEEP
	DAY/NIGHT DAILY ORBIT					9			
	TDRS AVAIL	7	8			9			10 11 12 13 14 15
	ISS TLM	05 1	122			+112+			122
	ORBIT NOTES	95	96 ISS-HAM-SM /	ASSIST⊕	VDS	97 -N2-VID-CAP-1	INSTL		98 99 100 101 102 103


2-25


























1	"Good Morning, Atlantis and thank you for calling the Mission Control Automated Call Center. We are experiencing an unusually high call volume on the TDRS to White Sands
2	link, due to multiple vehicles utilizing the satellite. Your patience is appreciated."
4	illik, due to multiple verilcles utilizing the satellite. Tour patience is appreciated.
5	"Please choose from one of the 135 options below"
6 7	"Press or say "1" for Space or Ground Network Techno-Babble."
8	"Press or say "2" for an NDC password reset."
9	"Press or say "3" for MPC/Crew Choice playback."
10	"Press or say "4" if you are experiencing unexpected RFI."
11	"Press or say "5" if you would like to perform a TDRS handover."
12	"Press or say "6" For Windows 7 migration issues."
13 14	<one later="" orbit="" shift=""></one>
15 16	"Press or say "135" to request a launch hold."
17 18 19	<beep -="" made="" selection=""></beep>
20	"Stand by while we connect your call"
22	<hold music=""> "Ground Control to Major Tom, Ground Control to Major Tom, take your</hold>
23 24	protein pills and put your helmet on"
25	"We apologize for the delay, please remain on the Air-to-Ground lines, your call is very
26 27	important to us."
28 29	HOLD MUSIC> "This is Major Tom to Ground Control, I'm stepping through the door and I'm floating in a most peculiar way"
30	"The player for helding and one only oble to proceed low data rate of this time, would you like
31	"Thank you for holding, we are only able to process low data rate at this time, would you like to remain on the line?"
33 34 35	<unintelligible comment=""> "#*&\$*@!!!"</unintelligible>
36 37	"I'm sorry, I didn't catch that we'll have GC work on the echoes."
38	"Please try your call again laterand KUDOS to you all from the Ground Control and
39	Operations Support Team! Goodbye."
40	, , , , , , , , , , , , , , , , , , , ,
41	"Atlantis/ISS, we are now resuming operational audio communications."
42	
43	-GC and the OST
44	
45	
46	
47	
48	
49 50	
J U	

51

1	YOUR CURRENT ORBIT IS: 213 X 206 NM									
2	NOTAMS -									
14	EDW - EDW 22L/04R IN USE. EDT 22R/04L IN EDW - LAKEBED RWYS GREEN EDW RWY 22L MLS AZIMUTH SINGLE STRINGR - LAKEBED RWYS GREEN NTU - RWY 05L/23R AND 14R/32L CLSD MRN - RWY 20 ALS OUT OF SERVICE FMI - TACAN NIM53 DECOMMISSIONED BEJ - CLOSED UNTIL 15 JULY ESN - RWY 03R/21L CLSD ESN - TACAN BAG78 OUT OF SERVICE GUA - TACAN UNZ105 OUT OF SERVICE FFA - NOT USABLE. IN CARETAKER STATUYQX - TACAN YQX74 DME ONLY YYR - TACAN UYR40 DME ONLY YYT - TACAN UYR40 DME ONLY YYT - TACAN YJT78 DME ONLY YJT - TACAN YJT78 DME ONLY BEN - NOT USABLE. NOT SUPPORTED IKF - NOT USABLE. NO AGREEMENT	RING								
23	NEXT 2 PLS OPPORTUNITIES:									
25 26 27	EDW22 ORB 94 – 5/22:32 SKC 7 220/14P22 EDW22 ORB 110 – 6/23:10 SKC 7 220/10P16									
28 29 30	OMS TANK FAIL CAPABILITY:									
31 32	NO									
33 34	LEAKING OMS PRPLT BURN:									
35 36	ALWAYS BURN RETROGRADE									
37 38	OMS QUANTITIES(%):									
39 40 41	L OMS OX = 37.90 R OMS OX = 37.74 FU = 37.97 FU = 37.32									
42 43	DELTA V AVAILABLE:									
44 45	OMS ARCS (TOTAL ABOVE QTY1)	362 FPS 34 FPS								
46 47 48	TOTAL IN THE AFT	396 FPS								
49 50 51	ARCS (TOTAL ABOVE QTY2) 63 FPS FRCS (ABOVE QTY 1) 34 FPS									
52 53 54	AFT QTY 1 AFT QTY 2	84 % 46 %								
55	THERE ARE NO FAILURE/IMPACT/WORK AROUND	S FOR TODAY.								

MSG 053 (28-0551) - FD07 TRANSFER MESSAGE

Page 1 of 8

Good morning, Sandy!

Thank you, and the rest of the crew, for all the hard work yesterday, which continues to keep you ahead of schedule on transfer. Today you should focus on finishing up packing the backside locations of the RSPs and then enjoy your off-duty time this afternoon.

Transfer Status:

Middeck: 59% complete
 MPLM: 48% complete
 TOTAL: 49% complete

The Transfer List Excel file, FD07_Transfer_List_STS135.xls, locations are:

• Shuttle: C:\OCA-up\transfer (KFX machine)

Station: K:\OCA-up\transfer

Transfer Notes

• TVIS Gyro stowage: In order to help you stow the TVIS Gyro in the F1_K1 location, OSO has uplinked MSG 54 (28-0558) Resupply Stowage Platform (RSP) R&R detailing the RSP strut removal plan we talked about last night. In summary, you'll be removing two struts from the left rear of the F1 RSP, folding out the vertical fence, stowing the gyro in the K1 location, and replacing the fence and struts. We've looked at alternate stowage locations for the gyro; however, all other options drive additional hardware location changes. Additionally, please wait to complete this activity until we receive confirmation that the new gyro has successfully spun up later today.

FD07 Choreography

- Middeck Return Item 727: Pack condensate sample
- Complete any RSP backside items not completed on FD06
- Stow return items in RSR blocked locations while RSP fences are folded

Please incorporate uplink pages as follows (we've listed the updates in the order they printed out for you):

MIDDECK TRANSFER LIST BOOK

 In the Middeck Transfer List **RETURN** tab

Replace the following pages:
Return 1

Return 2

Return 6 Return 10

Add the following page:

Return 11

MSG 053 (28-0551) - FD07 TRANSFER MESSAGE

Page 2 of 8

In the MPLM Return Transfer List **RETURN** tab Replace the following page: Return 38

MPLM RETURN TRANSFER LIST BOOK

FD08 Choreography

- Pack old PGT for return in MPLM after PGT C/O
- Transfer CubeLab Module-7 LMA Pack 2 (s/n 1001) to middeck.
- LiOH Swap:
 - o 20 unused STS-135 cans from middeck to ISS
 - 7 unused STS-132 and STS-133 cans from ISS to middeck
 - o 6 used STS-134 cans from ISS to middeck (if found)
- Uninstall pivot pin brackets at A2, A4, F2, & F4 RSPs and stow in MPLM for return (if backsides are complete).
- Transfer Micro-4 samples from ISS (CGBA-5) to middeck (CGBA-2).
- Continue packing MPLM for return.

Have a great day!

- STS-135 Transfer Team

28-0558 (MSG 054) RESUPPLY STOWAGE PLATFORM (RSP) STRUT R&R

Page 1 of 5 pages

OBJECTIVE:

Remove and replace RSP struts for access to rear fence stowage volume.

LOCATION:

MPLM

DURATION:

20 minutes

CREW:

One

MATERIALS:

None

PARTS:

None

TOOLS:

Digital Camera

ISS IVA Toolbox:

Drawer 1:

3/4" Combination Wrench (if required)

REFERENCED PROCEDURE:

None

28-0558 (MSG 054) RESUPPLY STOWAGE PLATFORM (RSP) STRUT R&R

Page 2 of 5 pages

1. ACCESSING

√Stowage removed from MPL1F2 Rack Bay for access to side of MPL1F1 Rack.

2. REMOVE RSP REAR STRUTS




Figure 1.- Overview of RSP rear parts with rack still rotated up.

2.1 Remove RSP Rear Side Strut from Horizontal Middle Rear Fence and Horizontal Bottom Rear Fence, tethered PIP pins (two). Temporarily stow. Refer to Figure 1.

NOTE

PIP pins secure adjacent fences to one another and are at the corners of adjacent M-01 and M-02 fences.

28-0558 (MSG 054) RESUPPLY STOWAGE PLATFORM (RSP) STRUT R&R

Page 3 of 5 pages

2.3 Remove tethered PIP pins (two) securing Vertical M-01 Fence to Horizontal Middle Rear Fence and Horizontal Bottom Fence. Refer to Figure 1.




Figure 2. - Top RSP Rear Tube Strut Bracket.

- 2.4 Remove retaining rings from PIP pins on RSP Rear Tube Struts (two, one per PIP pin).Refer to Figure 2.
- 2.5 Remove RSP Rear Tube Strut, PIP pins (two).Temporarily stow.Refer to Figure 2.

NOTE

- 1. The Jam Nuts on either end of the RSP Rear Tube Strut are threaded in opposite directions (Left-Hand and Right-Hand threads).
- 2. Both Jam Nuts will need to be loosened to allow adjustment of the RSP Rear Tube Strut.

28-0558 (MSG 054) RESUPPLY STOWAGE PLATFORM (RSP) STRUT R&R Page 4 of 5 pages

* If PIP Pins cannot be removed from RSP Rear Tube Strut

Brackets,

- 2.5.1 Loosen RSP Rear Tube Strut Jam Nuts (two), as required (3/4" Combination Wrench).
- 2.5.2 Turn RSP Rear Tube Strut to lengthen or shorten, as required.
- * 2.5.3 Remove PIP pins (two).
- 2.6 Swing Vertical M-01 Fence into MPL1F2 Rack Bay for stowage volume access.

3. STOWAGE

3.1 Stow hardware in RSP volume per transfer list.

4. INSTALL RSP REAR STRUTS

- 4.1 Swing Vertical M-01 Fence until aligned with PIP Pin clevices on Horizontal Middle Rear Fence and Horizontal Bottom Fence. Install PIP Pins (two) into Vertical M-01 Fence clevices. Refer to Figure 1.
- 4.2 Align RSP Rear Tube Strut into RSP Rear Tube Strut Brackets. Install PIP pins (two). √PIP Pins install easily (not forced), with some free wiggle.

* If PIP Pins cannot be easily installed into RSP Rear Tube Strut

Brackets.

Refer to Figure 2.

- 4.2.1 Loosen RSP Rear Tube Strut Jam Nuts (two), as required (3/4" Combination Wrench).
- 4.2.2 Turn RSP Rear Tube Strut to lengthen or shorten, as required.
 - 4.2.3 Install PIP pins (two).
- √PIP Pins install easily (not forced), with some free wiggle.
- 4.2.4 Hand tighten RSP Rear Tube Strut Jam Nuts (two).
- 4.3 Install retaining rings on PIP pins on RSP Rear Tube Struts (two, one per PIP pin).Refer to Figure 2.

28-0558 (MSG 054) RESUPPLY STOWAGE PLATFORM (RSP) STRUT R&R Page 5 of 5 pages

4.4 Install RSP Rear Side Strut (P/N SEG33112727-301) on Horizontal Middle Rear Fence and Horizontal Bottom Rear Fence, tethered PIP pins (two). Refer to Figure 1.

5. <u>CLOSEOUT</u>

- 5.1 Photo document rear RSP configuration (Digital Camera).
- 5.2 Notify **MCC-H** of task completion.